

Wendover Cricket Club's New Ground at Tring Road – Progress Photographs & the Pavilion's Envisaged Walk-through

Paul Duff has kindly produced a visual walk-through to show what the inside of the pavilion is intended to look like, via the following link . . .

[Wendover CC Tring Road.mp4](#) . . . which is about 4½ minutes long.

It won't be long now until it all comes together because Boom are still aiming to complete the pavilion works by 13th March. The regular Clerk of Works reports (latest one below) provide photos of recent progress. However, Agripower's works on the grounds and banks are due to be completed by 1st May but that will be dependent on favourable weather; apart from the playing surfaces, everything remains to be seeded.

From the Clerk of Works Report No.12 by Philip Newman MRICS, Chartered Building Surveyor, of his visit on 21st January 2026.

The view from the northwest corner of the cricket ground. In view the club house, and now the equipment shed (on the right):





The clubhouse from the northwest.
Inset the view in my last report



The clubhouse from the northeast.
Inset the view in my last report

Progress being made with the new access road and the footway crossing on Tring Road:



The clubhouse from the southwest:



The public footway with Tring Road on the right. The end of the Heras fencing on the left is where the tree stump was in place until removed following my last visit:



And looking down on the new access road:



The bi-fold screen installed on the north side of the clubhouse:



Ductwork etc. in the roof space:



The fan coil unit is in place over the clubroom upstand:



The site has become very muddy at the end of the haul road ...



... and around the other side of the building:



Another view of the site, taken from near Tring Road. Although there is a lot of surface water, the main cricket ground's land drainage appears to be working well with no evidence of laying water.

